

Uptime Corporation

High Speed Input Output Systems

Golden, Colorado, 15910 West 5th Avenue, 279-3351

February 18, 1965

Mr. Theodor H. Nelson
Box 1546
Poughkeepsie, New York 12603

Dear Sir:

In reply to your recent inquiry to Data Processing Magazine, we are happy to enclose the following material describing our SPEEDREADER 800 and SPEEDREADER 400 punched card readers:

SPEEDREADER 800 punched card reader general specifications dated August 19, 1964.

SPEEDREADER 400 punched card reader general specifications dated August 3, 1964.

For your information we are also enclosing general specifications on our SPEEDREADER 1500 dated January 12, 1965, and our SPEEDREADER 2000 dated August 18, 1964.

Prices on this equipment depend largely upon individual requirements and final configuration. Therefore, it is quite difficult to quote prices without knowing what the requirements would be.

Should you have questions or require additional information regarding this equipment, please do not hesitate to contact us.

Very truly yours,

Duane A. Strawn

Duane A. Strawn
Sales Department

DAS-rg

Enc.